

BTMA Daily Report

Tuesday, February 9, 2010

Weather: 17 to 31 Cloudy

Contract No 2 Collection and Conveyance Lines – Village of Bethel

Marks Contracting: None

No Work

Contract No 3 Pump Stations – Village of Bethel

Marks Contracting: None

No Work

Contract No 4 Waste Water Treatment Plant – Village of Bethel

Marks Contracting: None

Subcontractor: Dutchland:

WWTP

Dutchland verified the water level in the clarifying tank in train #2 has stabilized. The leak around the effluent pipe appears to be repaired.

Contract No 5 Waste Water Treatment Plant – Village of Frystown

Marks Contracting: None

Subcontractor: Dutchland:

WWTP

Dutchland verified the water level in the clarifying tank in train #1 has stabilized. The leak around the effluent pipe appears to be repaired.

Contract No 6 Mechanical (HVAC)

Shannon Smith: None

No Work

Contract No 7 Plumbing

TMI Commercial: None

No Work

Contract No 8 Electrical

JB Electric: None

No Work

Lateral Hookups

The following residents from the Village of Frystown and Bethel connected to the new sewage system:

Name	Address	System	Remarks
None			